

AGADIR - sweatshirt			
Description	• stretch ribbed bottom and cuff		
Maintenance	Maximum wash temperature: 40°C; do not bleach; do not dry clean; do not dry in a tumble dryer; ironing at low temperature (max 110°C) 	item	V109-0-00 black V109-0-01 red V109-0-02 navy V109-0-03 clay brown V109-0-04 anthracite V109-0-07 green V109-0-09 white
		standards	
		sizes	S – 4XL

SAFETY TECHNICAL SPECIFICATIONS

	<i>Test method</i>	<i>description</i>	<i>Cofra result</i>	<i>minimum requirement / range</i>
Background fabric	EN ISO 1833-1977, SECTION 10	Composition:	65% Polyester 35% Cotton	
	EN ISO 12127:1996	weight	280 g/m ²	
	EN ISO 13688:2013 4.2 (EN 14362-1)	Search of the aromatic and carcinogenic amines	OEKO-TEX [®] Standard 100	≤30 ppm
	EN ISO 13688:2013 4.2 (EN 1413)	The pH's determination from the watery extract	OEKO-TEX [®] Standard 100	3,5<PH≤9,5
	EN ISO 105-C06	Colour fastness to Laundering at 40°C		
		Colour change	4	1 - 5
		Staining:		
		diacetate	4	
		cotton	4-5	
		nylon	4	
		polyester	4	
		acrylic	4-5	
		wool	4-5	

	EN ISO 105-E04	Colour fastness to perspiration	Acidic	Alkaline	
		<i>Colour change</i>	4-5	4-5	1 - 5
		<i>Staining:</i>			
		diacetate	4-5	4-5	
		cotton	4-5	4-5	
		nylon	4-5	4-5	
		polyester	4-5	4-5	
		acrylic	4-5	4-5	
		wool	4-5	4-5	
	EN ISO 105-X12	Colour fastness to rubbing	dry = 4-5 wet = 4		1 - 5
	ISO 105-B02	Colour fastness to light			
		<i>Colour change</i>	5		1 - 5
	EN ISO 105-X11	Colour fastness to hot pressing (110°C)			
		<i>Colour change</i>			1 - 5
		Dry:	4-5		
		Wet:	4-5		
	EN ISO 12945-2	Determination of fabric propensity to surface fuzzing and to pilling	after 125 cycles: 3-4 after 500 cycles: 3-4 after 1000 cycles: 3 after 7000 cycles: 3		1 - 5
	ISO 12947-2	Determination of the abrasion resistance of fabrics by the Martindale method (12KPa)	>10000 cycles		